P810 Base Exploded View





1	BRACKET FOOT
2	BASE
3	MACHINE SCREW
4	BASE PANEL
5	SCREW
6	FOOT PAD